

FAULTY INPUT OF SUCTION PRESSURE

With some previous generation *FrigoPack*s there could be a problem with the sensing of the Suction pressure caused by a component failure (blue LED).

The ranges possibly affected can be analysed and cured as follows:

General fault finding

• Bridge two input terminals to **MAM** input module and check pressure reading on the *FrigoPack*E(I) FMV:

Bridge input terminals **3A-3B** temporarily with a piece of wire and read the internal pressure as follows:

Small keypad: AP01

Large keypad: 01:pe SUCT PRES

A pressure of 7.0 bar should be indicated. If 7.0 bar is not shown, then there is a problem with the analog input of suction pressure.

Connect a refrigeration manifold (REFCO or similar) and measure the suction pressure if a
pressure gauge is not fitted and compare with the *FrigoPackE(I)* FMV pressure reading in
bar:

 Small keypad:
 AP01
 Large keypad:
 01:pe SUCT PRES

The same pressure should be indicated.

<u>BUT</u>

If the pressure is higher than 7.0 bar, then *FrigoPack* will only show 7.0 bar. If the same pressure is not shown, then there is a problem with the analog input of suction pressure.

Methods of solving the problem

- Return the suspect / faulty FrigoPack to KIMO RHVAC for repair.
- Replace the external MAM module (green PCB) with a replacement module
- Make a temporary on-site repair as follows:
 - FrigoPackE FMV:
 - Link there following terminals:
 - Terminal **3B** on the external **MAM** module (on the green base) with the wire from the pressure transducer still connected to terminal **3B**
 - Terminal 3 on the *FrigoPackE* FMV

(control terminal on the right-hand side under the terminal cover) There is already a wire connection to this terminal so care is required.

High-pressure input

There have never been any problems with the high-pressure input to do not make any changes to the high-pressure input without referring to KIMO RHVACC first.